

### Application of Avery MPI cast films on irregular substrates issued: 25/01/2011

Avery MPI cast films have to be applied in the best possible manner in order to ensure that the product will perform as intended and designed. Successful application results in an adequate bond between adhesive and substrate. Please read the instructions for surface preparation of the substrate prior to application.

The information provided in this document can also be found on our website, [www.academy.averygraphics.com](http://www.academy.averygraphics.com). This website also contains instructional How-to videos and additional theory modules.

Prior to application or lamination, prints must be sufficiently dried in order to prevent negative influence on film properties or adhesion properties.

In general, a drying time of 24 hours will be sufficient. In case a lot of ink is deposited, materials may need up to 72 hours in order to be sufficiently dry.

When drying, material should **not** be tightly wound on a core, as the solvents are then unable to evaporate. The materials should be left to dry loosely, wound on a core or stacked in racks as sheets.

Properly dried images are always needed in order to benefit from each product's specific feature.

#### 1. Surface preparation

The surface has to be cleaned by:

1. Washing with a mild detergent solution, after which the surface should be rinsed and dried with a lint-free cloth.
2. Avery Surface Cleaner.

Many commercially available cleaning/degreasing products exist: the applicator should establish the suitability of a product prior to actual use. In addition, the following factors should be considered prior to any application:

Car wax and polish residues must be **completely** removed.

Paint surfaces must be completely dry, hardened and free of scratches. On most baked paints, films can be applied immediately after cooling down. Air-dried and car repair paints require at least one week to dry out before films should be applied. Solvent residues in painted substrates may adversely affect film adhesion and might cause excessive shrinkage or blistering.

Painted substrates for self-adhesive films should be prepared according to the paint manufacturer's instructions. Here, too, it is important to avoid solvent retention. Paint system components which are not compatible or do not adhere properly to each other may cause paint to be lifted when films have to be removed after use.

Special attention should be given to critical areas such as edges, corners, welding seams, rivets, corrugations and the like. These areas must be thoroughly cleaned and dried before application.

## TECHNICAL BULLETIN 5.9

### 2. Picture preparation

Before printing, it is required to have the right media profile installed and selected in your print server. The media profile contains a combination of information on printer / rip / ink / media. The right media profile not only produces the best colours but will also reduce the amount of ink deposited on the material, resulting in less influence of the solvent on the material properties. Media profiles are available via the Avery website.

After printing, digitally printed images on Avery MPI cast films should be thoroughly dried before application. In case a varnish is applied over the decal in order to protect the decal against abrasion, care should be taken that the image is dry before the varnish is applied to prevent residual solvent in the print. The recommended drying time after printing is at least 24 hours and preferably up to 72 hours. It is important that the material is not tightly wound on a core.

In case a material is overlaminated with an Avery DOL, make sure the right combination is chosen. Only the use of an Avery 1400 series cast laminate is recommended for corrugated or riveted surfaces in combination with the right cast base films (please check TB 5.3 for additional information).

### 3. Application methods

Avery MPI Cast films have a high degree of conformability compared to other cast vinyls, and the films show excellent results on 3D-shaped surfaces. The use of an industrial hot-air tool is needed to improve the ease of application.

After application it is absolutely necessary to re-heat those parts exposed to stretch, strain or other deformations to obtain their final shape. Re-heating will eliminate the applied tensions in the film. Always respect the minimum application temperatures as specified in the technical datasheets.

Avery MPI Cast films are designed for dry application on prepared surfaces. Although not recommended, it is possible to apply certain Avery Cast films using the "wet method", for flat applications only. Both methods will be explained in the following two sections of this document.

#### 3.1 Dry Application Method

When using the dry application method it is not strictly necessary to use application tape. The application tape can be laminated over the graphic for ease of positioning and to protect it against stretching and scratching. Hereafter this newly formed laminate will be referred to as film.

#### Application surfaces

This bulletin refers to five types of surfaces with short descriptions and instructions.

#### **Concave surfaces**

This hollow or bowl-shaped form implies that the material will be laid into a rounded or curved-in surface. Position the film over the entire surface area as explained in our Technical Bulletin 1.4. Remove (a part of) the liner and apply the film on the surface with the help of your thumb or a squeegee. Remove the application tape and start working the film into the hollow shape.

If convenient, some heat can be applied to soften the film, thus making the inlay process easier. The applied temperature should be between 35° and 50°C.

The use of hand gloves (dry or slightly wet) will make this process easier. Gently follow the form of the substrate until all the material has been positioned.

Apply heat over the entire area, especially over the concave part, in order to allow the film to adopt the shape of the substrate. The stretched parts of the film should be re-heated in a temperature range between 80° and 90°C. It is important that both the film and the substrate are heated to these temperatures. This is best achieved by re-heating gradually, instead of a short blast of heat. Let the film and the substrate cool down till room temperature prior to any cutting of edges or overlays, etc.

## TECHNICAL BULLETIN 5.9

### 3.1 Dry Application Method (*continued*)

#### **Convex surfaces**

This curved or rounded form implies that the material will be stretched around a curved-out surface. Position the film over the surface area as explained in Technical Bulletin 1.4.

Remove (a part of) the liner and apply the film on the surface with the help of a squeegee. Move around the convex area and apply gentle strikes until the film cannot stretch any further in order to avoid air being trapped.

Remove the application tape and start shaping the film with a felt squeegee or use hand gloves making gentle movements around the area. Remove air entrapment by punching small holes in the film and if convenient, use hot air to make the film more conformable. During the conforming process the applied temperature should be in the range between 40° and 50°C.

After completing the application, apply more hot air to the film in the temperature range between 80° and 90°C over the convex area and apply pressure again in critical areas using a squeegee covered with felt or hand gloves. Again, it is important that not only the film reaches these temperatures, but also the substrate should be heated to these temperatures. The best result is achieved by re-heating gradually instead of a short blast of heat. Let the film and the substrate cool down till room temperature prior to any cutting of edges or overlays, etc.

#### **Compound surfaces**



This is generally a complex form of concave and convex surfaces, which can be found one after another or even side by side. These shapes are frequently found in modern models of cars or vans. The method of application follows the description of the two individual shapes provided in the previous two sections.

#### **Corrugated surfaces**

Position the film to the application surface with a masking tape that can serve as a hinge (see Technical Bulletin 1.4). Ensure that the hinge is in a flat section of the surface. Only remove a small area of liner to prevent pre-sticking. Application to this type of surface has to be done systematically; section by section is the best approach. Deviation from this application sequence may result in pleats, which are sometimes difficult or even impossible to be eliminated.

Start the application at the hinge (continue section by section) and apply the film from the centre to the side of the film or printed graphic. This method will limit the occurrence of pleats.


While keeping the adhesive free from the substrate, apply the film with a plastic squeegee. Do NOT stretch the film, but follow the irregular shaped surface. Use the full width of the squeegee and press the film firmly down over the entire surface area. Vertical sections should be applied with vertical squeegee strokes. Make sure the film is applied correctly in the edges, corners, seams, etc. Remove the application tape after 3 to 5 minutes and re-squeegee the edges or corners.




## TECHNICAL BULLETIN 5.9

### 3.1 Dry Application Method (*continued*)


When edges and corners are re-squeegeed, make sure the material is fixed on the edges of the corrugation (see below), and work your way around the entire corrugation, just fixing the edges!!



Now, the application of the material in the corrugation can start. In order to be able to do so without forming pleats or creases, it is advised to wet the glove, using a water/soap mixture.




The next step is to heat the material gently, using a hot-air gun, to about 40°-50°C. It is advised to do small areas at a time.




## TECHNICAL BULLETIN 5.9

### 3.1 Dry Application Method (*continued*)



Now, start stretching the material in the corrugation, starting in the deepest part of the corrugation first. Make sure that the material is heated to remain in the 40°-50°C temperature range.



Continue your way around the corrugation, only focussing on the deepest part of the corrugation.




When all the deepest parts of the corrugation have been applied, the inside of the corrugation can be done. Again, make sure the material is heated to the required 40°-50°C, and work your way through the corrugation.




## TECHNICAL BULLETIN 5.9

### 3.1 Dry Application Method (*continued*)


With all the edges now properly applied, apply the material in the centre of the corrugation. Make sure that no air is trapped, by always leaving an opening for the air to escape.



Check the application for remaining bubbles. If you see any small air bubbles, remove them by making a small puncture, heat it a little and push out the air.



Then the final stage of the application starts. Using the hot air gun, the material should be heated to a temperature of approx. 80-90°C, especially in those areas where the material is stretched. Make sure that the heating is done gently, and the temperature is gradually increased. It is important that both the film and the substrate are heated to these temperatures. The best result is achieved by re-heating gradually, instead of a short blast of heat.



## TECHNICAL BULLETIN 5.9

### 3.1 Dry Application Method (*continued*)

#### ***Riveted surfaces***

Position the film to the application surface with a masking tape that can serve as a hinge (see Technical Bulletin 1.4). Ensure that the hinge is in a flat section of the surface. Only remove a small area of liner to prevent pre-sticking.

Start the application at the hinge and work towards the edges of the film or graphic. When a rivet is reached, push the film towards the rivet head with the squeegee and apply the film leaving an air "bubble" around the rivet. Maintain sufficient tension in the film to prevent pleats around the rivets. Once the film part or graphic has been applied (with the application tape still in place), use a needle to punch 4 or 5 holes around the rivet and proceed to apply the film with a plastic squeegee. After this stage has been completed, remove the application tape.

Gently push the air out of the entrapment by hand, using gloves or with a soft squeegee. Apply heat to the film around each individual rivet with a portable hot-air tool until the film softens. It is advisable to use a temperature range of 40°-50°C. Push the film further into shape around the rivet with your thumb (using gloves) or a felt covered squeegee.

Eventually the film can be moulded around the rivet head by means of a brush, using circular movements. Be aware to apply the pressure of the brush on the film only at room temperature and avoid scratching the surface.

Complete the application by applying hot air to the film using a temperature range of 80°-90° C. It is important that you heat both the film and the substrate to these temperatures. The best result is achieved by re-heating gradually, instead of a short blast of heat. Check and re-squeegee the edges of the rivets of the applied film or graphic, where required.

### 3.2 Wet Application Method

This application method is recommended for **flat surfaces only**. Do not use on concave, convex or compound surfaces.

#### **Do NOT use wet application method for Avery Easy Apply products.**

The film can be positioned on the substrate without adhering to it by wetting the surface with a 1% detergent solution in water. The detergent liquid provides slideability and repositionability to the pressure-sensitive film until the water film has been removed. A plastic squeegee can be used for the removal of the water layer. Start squeegeeing from the centre towards the edges of the film or graphic and gradually increase the applied force until almost all water has been removed. Repeat this process several times.

The advantage of the wet application method is that during application the film can be applied without the use of application tape. However, adhesive build-up via this application method will take much longer than under dry conditions. In general this means longer application times for certain areas since drying has to occur prior to the finishing touch of a job.

If an application tape has been used on the film it is advisable to check on the build-up of adhesion at the edges in order to determine the right moment for removal of the tape. This time span can be from 1 hour up to 6 hours, depending on the kind of substrate or the wetness of the application tape, etc. If the tape is removed too early, its removal may cause the film to lift from the substrate and consequently permanent surface imperfections or bubbles may be introduced.

## TECHNICAL BULLETIN 5.9

### Note:

- The wet method should **not** be used on riveted, concave and compound surfaces. Water will be encapsulated, and it is impossible to remove this water totally. As a result, the film may be lifted in rims, edges and compounded curves at a later stage.
- On convex surfaces the delay in adhesive build-up may jeopardise the overall performance of the product during its final product utilisation.

### 4. Recommended use for cast vinyl series

Product name	Description	Features	Air Release	Slideable	Repositionable	2D Surfaces		3D Surfaces		
						Un-laminated	Laminated with DOL 1000 series	Un-laminated	Laminated with DOL 1030 DOL 1130	Laminated with DOL 1460 DOL 1480
MPI 1900 MPI 1900 Easy Apply MPI 1906 AP	Conformable Promotional Cast vinyl	Grey Coating for High opacity	no	no	yes	+	+	+	+	+
MPI 1005 Supercast	Ultra Conformable Cast vinyl	Grey Coating for High opacity Highly Durable Long Term Removable	no	no	no	+	+	+	+	+
MPI 1040	Conformable Clear Cast vinyl	Excellent clarity Virtually no shrinkage	no	no	no	+	+	+	+	+
MPI 1004 Easy Apply	Conformable Cast vinyl with Air Release	Grey Coating for High opacity Highly Durable Long Term Removable Air Release	yes	no	yes	+	+	+	+	+
MPI 1005 Supercast Easy Apply RS	Ultra Conformable Cast vinyl with Air Release	Grey Coating for High opacity Highly Durable Long Term Removable Air Release, Repositionable & Slideable	yes	yes	yes	+	+	+	○	+

○ = when applied on concave surfaces make incision (after reheating) to relieve tension